

Information about the SeeStar S50 Accessories

- Extract the STL Files from the ZIP File.
- Print the STL Files. Most you only need a copy. You will need to print 3 copies of the tripod leveler feet.
- No assembly needed.
- Place the insert into the box.
- Place the printed caps into the insert.
- There is one extra slot for your solar filter.
- Put the cover on the box.
- Screw the two parts of each tripod leveler feet together.
- The tripod leveler feet and the dew shield do not go in the box.